

## 2000 Tahoe Z71 4x4 (2000 USD)



Location **Hawaii** https://www.genclassifieds.com/x-501121-z



2000 Tahoe, 5.7 Z71 Blown Head Gasket (5/20) so it will start and has lots of power. Water pump when out and temp gauge sensor must be not reading correctly because it never showed hot. Swap motors or just change out head gasket, water pump, throw in some new oil and you're rolling. I'm not going to fix it this time. Just put in a new Fuel pump, plugs, wires, cap, rotor. 4x4 works great.

Text or email only please. \$2000 is FIRM, I paid \$1100 just for the new tires not to long ago and no I don't want to trade. No I won't hold it for you. First person with cash gets it. Bring a trailer or Tow Truck. Sorry about Photos not sure why CL is uploading them upside.

	2000	Tahoe	271	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	271	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
3	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	<b>Z</b> 71	4×4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4×4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5
	2000	Tahoe	Z71	4x4
	https://www 01121-z	v.genclassii	fieds.co	m/x-5